

Enter Air Services Capability List (EAS-CL)



Document no.: EAS/M/CapabilityList

Enter Air Services Capability List

APPROVED COMPONENT MAINTENANCE CAPABILITY LIST

Item	Cat.	Description	P/N	Manufacturer	CMM	Additional req. doc.	Capability level	Remarks/ Limitations
1	C-15	Cylinder and Valve Assembly	806835-01, 808433-01	Avox Systems Inc.	35-18-35	SAE AIR 1059	REPAIR	Charging procedure
2	C-15	Oxygen Cylinder and Valve Assembly (CFFC)	B42365-1	Cobham	35-22-02	N/A	REPAIR	Filling a Partially Filled Cylinder and Valve Assy
3	C-15	Cylinder and Valve Assembly	801307-XX	Avox Systems Inc.	35-23-07	SAE AIR 1059	REPAIR	CVA Charging procedure XX€ <00-11;20-25>
4	C-15	Portable Cylinder Assembly	5500 SERIES and 5600 SERIES	Avox Systems Inc.	35-32-18	SAE AIR 1059	REPAIR	Charging procedure
5	C-15	Portable Oxygen Cylinder Assembly	3553 SERIES	Avox Systems Inc.	35-35-53	SAE AIR 1059	REPAIR	Charging procedure
6	C-15	Portable Cylinder Assembly	803668-01, 807434-01, 9700 SERIES, 9800 SERIES	Avox Systems Inc	35-31-55	SAE AIR 1059	REPAIR	Charging procedure
1	C-6	Trolley	TL060125	ZODIAC AEROSPACE	25-22-78	25-22-78 IPL	REPAIR	N/A
2	C-6	Trolley	TL500001	ZODIAC AEROSPACE	25-29-29	25-29-29 IPL	REPAIR	N/A
3	C-6	Trolley	TK075109	ZODIAC AEROSPACE	25-22-80	25-22-80 IPL	REPAIR	N/A
4	C-6	Trolley	TK721068	ZODIAC AEROSPACE	25-31-697	25-31-697 IPL	REPAIR	N/A
5	C-6	Trolley	MK618-37 MK618-3701	IACOBUCCI ATS	25-30-29	N/A	REPAIR	N/A

Enter Air Services Capability List

6	C-6	Trolley	TC02-102A1 TC02-102A1001 TC02-102A1CA TC02-102A1888 TC02-102A1HNA	DIETHELM KELLER AVIATION	25-35-88	N/A	REPAIR	N/A
7	C-6	Trolley	CM2002-102()	KORITA AVIATION	25-30-19	SAE AS8056	REPAIR	N/A
8	C-6	Trolley	CM1001-102()	KORITA AVIATION	25-30-14	SAE AS8056	REPAIR	N/A
9	C-6	Trolley	TK075020	DRIESSEN	25-37-63	25-37-63 IPL	REPAIR	N/A
10	C-6	Trolley	TK075056	DRIESSEN	25-37-63	25-37-63 IPL	REPAIR	N/A
11	C-6	Trolley	TL123003	DRIESSEN	25-20-09	25-20-09 IPL	REPAIR	N/A
12	C-6	Trolley	TK500001	ZODIAC AEROSPACE	25-29-30	25-29-30 IPL	REPAIR	N/A

Enter Air Services Capability List

APPROVED NDT(Non-Destructive Testing) PROCEDURES

EDDY CURRENT TESTING (ET)	
1.	737 NDT Manual Part 6, 51-00-00 Procedure 4
2.	737 NDT Manual Part 6, 51-00-00 Procedure 23
3.	737 NDT Manual Part 6, 53-30-00 Procedure 5
4.	737 NDT Manual Part 6, 51-00-00 Procedure 16
5.	737 NDT Manual Part 6, 51-00-00 Procedure 3
6.	ATR 72, NDT Manual - PART 6
7.	Embraer Legacy 650, NDT Manual - 3240-74 - PART 6, Procedure 3 (Pencil Probe) i.a.w. CMM 32-49 -11, Part Number 3-1641
8.	Bombardier BD -100, Goodrich Corporation Component Maintenance Manual Nose Wheel Assembly P/N 3-1610, Temporary revision No 32-1, 31-2, 23-2 (32-48-29)
9.	Embraer ERJ 145, Goodrich Corporation Component Maintenance Manual Main Landing Gear Wheel Assembly P/N 3-1641 Temporary revision No 32-10, 32-9, 32-8, 32-7, 32-6, (32-49-11)
10.	Embraer ERJ 135.../145., Goodrich Corporation Component Maintenance Manual Nose Landing Gear Wheel Assembly P/N 3-1622 Temporary revision No 32-10, 32-2, 32-1, (32-49-08)
11.	737 NDT Manual Part 6, 51-00-00 Procedure 14
12.	737 NDT Manual Part 6, 53-10-54 11
13.	737 NDT Manual Part 6, 53-30-00 Procedure 3
14.	737 NDT Manual Part 6, 53-30-00 Procedure 4
15.	737 NDT Manual Part 6, 53-30-00 Procedure 5
16.	737 NDT Manual Part 6, 55-10-27
17.	HA-420 i.a.w. Repair memo RM-420-51-04 – HIGH FREQUENCY EDDY CURRENT INSPECTION

ULTRASONIC TESTING (UT)	
1.	737 NDT Manual Part 4, 51-00-00 Procedure 1
2.	737 NDT Manual Part 4, 51-00-00 Procedure 2
3.	737 NDT Manual Part 4, 51-00-01

Enter Air Services Capability List

4.	Service Bulletin CFM56-7B S/B 72-1033
5.	Service Bulletin SF340-61-95 (SAAB 340 PROPELLER)

<i>Date, Quality Manager's signature and stamp</i>
14.03.2024 r.